SECRET

CODY 6 of 6

7 August 1958

BEST APRIL	A STEP OF THE	****	
F12-7-113	ARTEN	2121	

: Special Assistant to the Director for Flamming and

Development and Deputy Director, DPS

THRU

Director of Development and Procurement, DPS

25X1A 25X1A SUBJECT

	Pield					Scott	and.	
ſ		to	De	tach	nen'	ts.		

1. Dr. R. Scott and the undersigned will be at Detachment B from 12 August to 16 August. At Detachment C from 19 August to 26 August. Items which will be covered during this time are stated in the following paragraphs.

2. Quality Control

\$

- A. Present and discuss Headquarters Photo Team trip report with Detachment Commanders.
- B. Present and discuss with Detachment Commander Dr. Scotts letter to Mr. Bissell. Letter is report of meeting with Hycon factory personnel, Detachment Photo Supervisors and Dr. Scott in Washington, D. C. 8 July 1958.
- C. Determine reason for non-compliance with SOP 7 dated 17 March 1957; Subject: Photo Analysis-S Curve. MOTE: This SOP was written at the Detachments by numbers of the Headquarters Photo Team. All detachments acknowledged receipt of Analysis Hits in early April 1958.

D.	If necessary	indoctrinate	personnol	in analysis	kits
	D.	D. If necessary	D. If necessary indoctrimate	D. If necessary indoctrinate personnel	D. If necessary indoctrinate personnel in analysis

25X1A

E. Study test mission take (See 1428 (OUT 81808) and 1470 (OUT 81878)) to determine quality and to isolate factors Approved For Release 2002/10/29: CIA-RDF63-00313A000600010030-2

SECRET

- F. Discuss quality discrepancies noted in missions now at HTA.
 - G. Check optics of configurations.
- H. Determine cause and solution to fogging of Driftsight and Tracker bubble.

3. Configurations, General

- A. Discuss configuration malfunctions and action being taken to remedy them.
 - B. Check spare parts status.
- C. After appraisal of all facts, determine realistic maximum mission rate for B configuration.

25X1A 25X1A

D.	Check	and res	edy T	recker,	Hand	Contro	l. and	Drift	31	ght
Problems.					P&E,					
at Detach	ment B	. Dr.	3cott	and I	will e	ITLASA.	Detech	ment	C	to
establish	need :	for			at the	t Dets	elment			

- E. Assure shipping of one (1) 24" camera from Detachment B to Detachment C via M and O. <u>MOTE:</u> Detachment B has 10 cameras, Detachment C 8 cameras. During last visit of Photo Team, Detachment B was instructed to send camera to M and O but to date have not complied.
- F. State type data which should be included in all TWX mission reports.

4. Personnel

- A. Observe attitude and technical ability of personnel.
- B. Through Photo Supervisor get names of personnel the would possibly sign on for another year.

5. Film

- A. Check stocks to determine if film is being properly rotated.
 - B. Check area for empty spools and boxes.
 - C. Check status of 70 kM dupe material and spools.

A. Check 70 MM processor and spare parts.

B. Observe _____operations, noting condition of processors, techniques used and caliber of personnel.

7. System 4

25X1A

25X1A

25X1A

25X1A

25X1A

25X1A

25X1A

SA/PD/DCI: bas
Distribution:
Orig. - SA/PD/DCI - Dep. Dir., DPS
2. - Dir. of D and P, DPS
3. - Dir. of OPS, DPS
4. - (copy to Dr. Scott)
6. - Chrono (Contracts)